## IECEx Quality Assessment Report Summary: GB/SIR/QAR07.0040/07 details

QAR Summary :			
QAR Reference Number *: (automatic numbering)	GB/SIR/QAR07.0040/07		
Related QARs:	GB/SIR/QAR07.0040/06 GB/SIR/QAR07.0040/05 GB/SIR/QAR07.0040/04 GB/SIR/QAR07.0040/03 GB/SIR/QAR07.0040/02 GB/SIR/QAR07.0040/01 GB/SIR/QAR07.0040/00		
Status*:	Issued		
QAR Free Reference Number*:	70207890		
Audit Date*: (yyyy-mm-dd)	2018-12-11		
Date of Issue*: (yyyy-mm-dd)	2019-01-09		
Details of change*:	Recertification	on Audit	
Valid until*: (yyyy-mm-dd)	2022-01-24		
Site(s) audited*:	International Metal Engineering Pte. Ltd Blk 13, Toa Payoh Lorong 8 #06-05 Braddell Tech Park Singapore 319261		
Issuing ExCB*:	SIR - SIRA Certification Service		
Manufacturer*:	International Metal Engineering Pte. Ltd Blk 13, Toa Payoh Lorong 8 #06-05 Braddell Tech Park Singapore 319261		
Location of Manufacture*:	Singapore		
Product information*:	Enclosures, Terminal Boxes and Terminals, Cable Attachments (Plugs, Sockets, Glands and Fittings)		
Protection concept*:	Ex d, t, ia/ib, e		
Related IECEx Certificates: (automatic linking)			
Related Certificates: (manual insertion)			
Related IECEx Certificates for previous versions:			
	ExCB	CoC and Status	Totals
	▼FMG		2
		IECEx FMG 14.0006U issue: 0 [Current]	
		IECEx FMG 14.0006U issue: 1 [Current]	
	▼SIR		43
		IECEx SIR 07.0082X issue: 0 [Current]	
		IECEx SIR 07.0111U issue: 0 [Current]	
		IECEx SIR 07.0111U issue: 1 [Current]	
		IECEx SIR 07.0111U issue: 2 [Current]	
		IECEx SIR 07.0111U issue: 3 [Current]	
		IECEx SIR 07.0111U issue: 4 [Current]	

IECEx SIR 07.0111U issue: 5 [Current] IECEx SIR 08.0025U issue: 0 [Current] IECEx SIR 08.0025U issue: 1 [Current] IECEx SIR 08.0025U issue: 2 [Current] IECEx SIR 08.0025U issue: 3 [Current] IECEx SIR 08.0025U issue: 4 [Current] IECEx SIR 08.0091X issue: 0 [Current] IECEx SIR 08.0091X issue: 1 [Current] IECEx SIR 08.0091X issue: 2 [Current] IECEx SIR 08.0126U issue: 0 [Current] IECEx SIR 08.0126U issue: 1 [Current] IECEx SIR 08.0126U issue: 2 [Current] IECEx SIR 08.0126U issue: 3 [Current] IECEx SIR 08.0126U issue: 4 [Current] IECEx SIR 08.0126U issue: 5 [Current] IECEx SIR 09.0006U issue: 0 [Current] IECEx SIR 09.0006U issue: 1 [Current] IECEx SIR 09.0006U issue: 2 [Current] IECEx SIR 09.0118U issue: 0 [Current] IECEx SIR 09.0118U issue: 1 [Current] IECEx SIR 10.0075 issue: 0 [Current] IECEx SIR 10.0075 issue: 1 [Current] IECEx SIR 10.0075X issue: 2 [Current] IECEx SIR 10.0091X issue: 0 [Current] IECEx SIR 10.0091X issue: 1 [Current] IECEx SIR 10.0102U issue: 0 [Current] IECEx SIR 10.0132X issue: 0 [Current] IECEx SIR 10.0132X issue: 1 [Current] IECEx SIR 10.0142 issue: 0 [Current] IECEx SIR 10.0142 issue: 1 [Current] IECEx SIR 10.0177X issue: 0 [Current] IECEx SIR 10.0177X issue: 1 [Current] IECEx SIR 12.0150U issue: 0 [Current] IECEx SIR 12.0150U issue: 1 [Current] IECEx SIR 12.0151X issue: 0 [Current] IECEx SIR 12.0151X issue: 1 [Current] IECEx SIR 14.0016U issue: 0 [Current]

45

Comment:

Attachment:

Last modified: 01/23/2019 01:08:46 PM

Copyright © IEC-IECEx 2019 , Geneva, Switzerland. All rights reserved.